

Arbor Villebois Townhomes Construction Defect Matrix

Lot Number	Defect:					
	Improper SPF/Whitewood Trim Installation	Omitted Flashing	Reverse Lap Flashing	Improper Sealant Joint	Improper Window Installation	Improper Cedar Shingle Application
210	X	X	X	X	X	
211	X	X	X	X	X	
212	X	X	X	X	X	
213	X	X	X	X	X	
214	X	X	X	X	X	
215	X	X	X	X	X	
216	X	X	X	X	X	
217	X	X	X	X	X	
218	X	X	X	X	X	
219	X	X	X	X	X	
77	X	X	X	X	X	
78	X	X	X	X	X	
79	X	X	X	X	X	
80	X	X	X	X	X	
81	X	X	X	X	X	
82	X	X	X	X	X	
83	X	X	X	X	X	
84	X	X	X	X	X	
85	X	X	X	X	X	
86	X	X	X	X	X	
311	X		X	X	X	X

Arbor Villebois Townhomes Construction Defect Matrix

Lot Number	Defect:					
	Improper SPF/Whitewood Trim Installation	Omitted Flashing	Reverse Lap Flashing	Improper Sealant Joint	Improper Window Installation	Improper Cedar Shingle Application
312	X		X	X	X	X
313	X		X	X	X	X
314	X		X	X	X	X
315	X		X	X	X	X
316	X		X	X	X	X
317	X		X	X	X	X
318	X		X	X	X	X
69	X			X	X	X
70	X			X	X	X
71	X			X	X	X
72	X			X	X	X
73	X				X	X
74	X				X	X
75	X				X	X
76	X				X	X
18	X				X	
19	X				X	
20	X				X	
21	X				X	
22	X				X	
23	X				X	

Arbor Villebois Townhomes Construction Defect Matrix

Lot Number	Defect:					
	Improper SPF/Whitewood Trim Installation	Omitted Flashing	Reverse Lap Flashing	Improper Sealant Joint	Improper Window Installation	Improper Cedar Shingle Application
24	X				X	
25	X				X	
31	X				X	X
32	X				X	X
33	X				X	X
34	X				X	X
35	X				X	X
36	X				X	X
37	X				X	X
38	X				X	
39	X				X	
40	X				X	
41	X				X	X
42	X				X	X
43	X				X	X
46	X				X	
47	X				X	
48	X				X	
334	X	X	X		X	
335	X	X	X		X	
336	X	X	X		X	

